

# Small Decal Application Instructions

Tools required: Application squeegee, masking tape, alcohol and a straight pin.

For best results air and surface temperature should be 60 to 100 degrees F.



## Step 1

The application surface must be free of dirt, grease and wax. Wipe the surface with a mild cleaner or alcohol. Position the decal and tape across the top with a piece of masking tape



## Step 2

Flip decal completely over using the application tape as a hinge. Remove the liner by pulling it up sharply over itself in a slow deliberate motion.



## Step 3

Fold decal back down in place and tightly hold it above the surface.



## Step 4

Using the application squeegee, start at the top center and apply moderate to strong even pressure down and out to the edges. Keep the squeegee edge flat to the decal.



## Step 5

Work from the center left and center right to evenly force the air out and the decal down onto the substrate. Keep the squeegee edge flat on the decal.



## Step 6

Work back and forth moving down each time until the decal has been completely applied.



## Step 7

Remove the masking tape from the top of the decal.



## Step 8

Start removing the application tape by pulling firmly from the upper corner back over the decal. It is important to keep application tape as close to the surface possible while pulling down.



## Step 9

After the application tape has been completely removed, be sure all decal edges are securely attached. Use the provided squeegee to properly adhere edges.



## Step 10

Use the straight pin to puncture any air bubbles that may remain and use the provided squeegee to press out the air.



27676 S.W. Parkway Ave.  
Wilsonville, OR 97070

If you need further assistance call us toll free 800-547-6841 or contact us at our web site [gillespie-graphics.com](http://gillespie-graphics.com)